

S5860-48SC Switch

FSOS Software Release Notes

Models: S5860-48SC

1. Version Information

1.1 FSOS 11.0(5)B13S4 Basic Information

Version Number	FSOS 11.0(5)B13S4
Applicable Products	S5860-48SC
Version Type	Official Version
Release Date	2022-3
BaselineVersion	11.0(5)B13S2

Reason of Release Renew and revised WEB functions

Using **show version detail** commands to check version number , examples are as follows:

```

FS#show version detail
System description      : FS Campus Switch (S5860-48SC) By FS.COM Inc
System start time      : 2022-03- 30 14:21:08
System uptime          : 0:01:25:21
System hardware version : 1.00
System software version :S5860_FSOS 11.0(5)B13S4
System patch number    : NA
System software number  : M11503503302022
System serial number   : MACCF03301420
System boot version    : 1.3.8.ca18d14(180905)
System core version    : 2.6.32.79dc524d43b8ed
System CPU partition   : 3
Module information:
  Slot 0 : S5860-48SC
    Hardware version    : 1.00
    Boot version        : 1.3.8.ca18d14(180905)
    Software version    : S5860_FSOS 11.0(5)B13S4
    Software number     : M11503503302022
    Serial number       : MACCF03301420

```

1.2 FSOS 11.0(5)B13S2 Basic Information

Version Number	FSOS11.0(5)B13S2
Applicable Products	S5860-48SC
Version Type	Official Version
Release Date	2021-8
BaselineVersion	11.0(5)B13S1
Reason of Release	Renew and revised WEB functions

Using **show version detail** commands to check version number , examples are as follows:

```
FS#show version detail
System description      : FS Campus Switch (S5860-48SC) By FS.COM Inc
System start time      : 2021-07- 16 17:37:28
System uptime          : 4:16:04:14
System hardware version : 1.00
System software version :S5860_FSOS 11.0(5)B13S2
System patch number    : NA
System software number  : M16064307162021
System serial number   : 1234942570067
System boot version    : 1.3.8.ca18d14(180905)
System core version    : 2.6.32.c557c01d43b8ed
System CPU partition   : 3
Module information:
  Slot 0 : S5860-48SC
    Hardware version    : 1.00
    Boot version        : 1.3.8.ca18d14(180905)
    Software version    :S5860_FSOS 11.0(5)B13S2
    Software number     : M16064307162021
    Serial number       : 1234942570067
```

2.Problem Solved

2.1 FSOS 11.0(5)B13S4 Problem Solved

ID	Summary
1	The AAA enable authentication failed
2	The web side only allows the administrator account to log in, and requires the ability to add user accounts to log in.
3	Port Mirroring board, only one set of mirrors can be configured on the web side, but multiple sets can be configured at the same time on the command line
4	Clicking on the Browse button in the Key of User section is unresponsive
5	The product does not support ERPS function

2.2 FSOS 11.0(5)B13S2 Problem Solved

ID	Summary
1	The ARP table item list cannot display the specified number of items
2	The upgrade function on the WEB is unavailable, and it prompts failure
3	The footer link FS community cannot be opened after switching language
4	The STP configuration on the WEB does not display, and the device does not support show spanning-tree WEB info
5	The traceroute function on the WEB cannot be used, and the device-side commands are not supported
6	The one-click collection function on the WEB cannot be used, and the device-side commands are not supported
7	Sometimes the mirror configuration cannot be configured abnormally, and the interface does not display after the configuration is successful