

FS-WLA-LC4-8C-E/FS-WLA-SC8-8C


FIBER TERMINATION BOX

Quick Start Guide **V2.0**


1

Product View

- Pigtail wiring
- Fiber wiring
- Installed cable



FS-WLA-LC4-8C-E




FS-WLA-SC8-8C

2


Accessories



8X (29669)
16X (18000)



4X



4X




8X




4X

3




4




5



Step1: Stripping fiber cable.



Step2: Remove the screw, fix the cable in the slot, mounting screws and then tighten the cable tie.




Step3: Tighten the screws to lock Mylar.




NOTE: The plastic splice tray can be removed by removing the screws on the back.

6



Step1: Connect pigtail to adapter.




Step2: Spliced fiber in heat shrinkable tube.



Step3: Fix the heat shrinkable tube to the slot.





NOTE: Adjust the mounting holes to desired distance.

